

Welding Fumes Picture This



3 STEPS TO RISK ASSESSMENT + EXPOSURE TO WELDING FUMES

- 1 Identify the hazard**
- 2 Know the possible harm**
- 3 Use the appropriate control measures**

Visit www.safesg.com/management for more information.
Call the Ministry of Manpower helpline 6271 0111 to report unsafe work practices.

  

Source: <https://www.tal.sg>