
Mobile Elevated Work Platforms (MEWPs) Stats and Facts



FACTS

- 1. **Inadequate Operator Training:** Workers without comprehensive training on MEWP operation, hazard recognition, and emergency procedures risk falls, entrapments, or tip-overs due to improper use or unfamiliarity with controls.
- 2. **Missing Fall Protection:** Failure to use guardrails, harnesses, or lanyards on MEWP platforms, especially Group B (boom lifts), increases fall risks, particularly at heights above 6 feet.
- 3. **Improper Setup:** Operating MEWPs on uneven, unstable, or soft ground without stabilizers or outriggers can cause tip-overs, endangering operators and nearby workers.
- 4. **Overloading Platforms:** Exceeding manufacturer-specified weight limits with workers, tools, or materials destabilizes MEWPs, leading to potential collapses or tip-overs.
- 5. Lack of Pre-Use Inspections: Skipping daily inspections of MEWP components (e.g., hydraulics, controls, guardrails) can allow undetected defects, increasing accident risks.
- 6. **Environmental Hazards:** Using MEWPs in high winds, rain, or near power lines without adhering to manufacturer guidelines risks tip-overs, electrocutions, or entrapments.
- 7. **Inadequate Rescue Plans:** Absence of practiced rescue plans for entrapments, falls, or mechanical failures delays emergency responses, potentially worsening outcomes for operators.

STATS

- OSHA reported in 2023 that MEWP-related violations were among the top 10 construction safety citations, with 15% linked to inadequate training or missing fall protection.
- WorkSafeBC noted in 2022 that 12% of construction fall injuries in British Columbia involved MEWPs, with 40% due to improper setup or overloading.
- A 2021 OSHA Outreach Courses report stated that from 2019—2020, 736 MEWP incidents affected 768 individuals, with 172 fatalities, primarily from falls and tip-overs.
- The Canadian Centre for Occupational Health and Safety (CCOHS) reported in 2023 that workplaces with mandatory MEWP operator training reduced accident rates by up to 22%.
- A 2022 Journal of Safety Research study found that 65% of MEWP injuries were caused by falls, entrapments, or tip-overs, preventable with proper training and

inspections.

• A 2021 Statistics Canada survey indicated that 10% of construction workers reported near-miss incidents with MEWPs, often due to inadequate hazard assessments or weather-related risks.