

# Plastic Molding Safety Infographic





## WARNING



Moving platens and dies on PLASTIC INJECTION MOLDING MACHINES can crush, dismember, snag, hit, and entrap, causing serious injury or death.

- Use safeguards to protect individuals.
- Keep hands and body clear while operating.
- Restrain loose clothing and long hair.
- Do not wear jewelry.

Dies, die parts, and plastic material can be ejected from point of operation, causing serious injury or death.

- Use safeguards to protect individuals.
- Always wear personal protective equipment.

Use electrically interlocked safety blocks, platen locks, or other die/platen support means when repairing, adjusting, or cleaning. Lock out all energy before servicing.

This sign is not intended to cover all safety hazards.

 creative safety supply, inc. 800-777-0800 F1002008-14

Source: <https://www.creativesafetysupply.com>