

Acoustical Work – Staying Safe During Acoustical Work Fatality File



Employee Is Injured in Fall from Scaffold Ladder

On November 10, 2010, Employee #1 was working from a rolling scaffold, installing acoustic ceiling tiles. Employee #1 climbed down the scaffold's fixed ladder to talk to the general contractor's foreman and he slipped from the ladder and fell to the concrete floor below. Emergency services were called, and Employee #1 was transported to a local hospital via ambulance. Employee #1 was diagnosed with a closed head injury and a ruptured spleen. Employee #1 was admitted to the hospital, where he remained under observation for 4 days. Employee #1's injuries healed without surgical intervention, and he was reevaluated after 3 weeks, at which time he was released to return to his normal activities.

Source: <https://www.osha.gov>