

# Embracing Change in the Workplace – Picture This



**What's wrong in this picture?** We use power tools and other power equipment in the construction industry for one simple reason: they're stronger than we'll ever be. Some people fail to realize that and put themselves in peculiar situations and many times set themselves up for an injury.

Such was the case when two construction workers were using a gas powered auger to dig a hole in some asphalt. The machine ended up getting stuck and then proved too much to handle for the poor guys. One was smart enough to let go, but the other decided to hang on to the handle, as the machine whipped him around like a rag doll, sending him flying into a pile of wood.