


# Picture This! Doubling Up on Dimwit Behavior



We're not sure what sort of work these guys thought they would be performing on this day, but they certainly didn't come prepared with any equipment to keep themselves safe while working at heights. It's ironic to see the safety cones set up on the ground at left. Safety first, right guys? (WorkSafe Victoria, Australia)